# SOUTH PRODUCTION NOTES

December 23, 2014 7-3 Shift Notes

BASF EMPLOYEES
62 Last Recordable
542 Last Lost Time

Be sure to check weigh all bags off of the calciners and fill out the log sheet downstairs by the scale and Attach "Packaged By" label with your initials.

All: check your CBT's to be sure they are finished up to the end of the Year

# #1 MED / AL 4126 1/16th:

On hold until the fluid coupling can be repaired. Mix 15 more batches including the one in the mixer. Need to complete lot 45 on calciner

Midnight shift: On hold for maintenance.

Day shift: On hold for maintenance

Afternoon shift: Fluid coupling replacement scheduled for Tuesday

# #1 RC /AL 4126 1/16th:

Hold until MED line up again (mixer issues). Need to ask Kristen if she wants to run the 3 bags on floor through the calciner.

Midnight Shift: Hold.

Day shift: Hold

Afternoon shift: Hold

Exhaust to F1 until we are feeding again, then to Trimer

# #2 MED line / Cu-0860:

Spiral repaired. Be sure to use wet mix on every batch.

Midnight shift: holding

Day Shift:

**Afternoon Shift: Continue** 

## #2 RC/ Cu 0860:

Bladder on bag off station should be working now. Still need to feed bags on 1<sup>st</sup> floor (Bodmann will advise)

Midnight shift: running

Day Shift:

Afternoon Shift: Feeding the bag as described above... trying to line out syntron. Syntron settings seemed to be good at 9 seconds on, 15 seconds off, 35% vibration. Bodmann notified of these settings so MOD

**Exhaust to F1** 

# #3 MED/ D-1780:

Running. Door seals have been replaced.

Midnight shift: Continued

Day Shift:

**Afternoon Shift: Continue** 

## #3 RC / D 1780:

Continued. Screener skimmed over, installed Cleaning kit. Per Bodmann take oversized line to a drum for approx. 2 hr to try and get rid of the little balls of material that are coating the Screener. Label as oversized and put in red zone.

Midnight shift: Continue

Day shift:

**Afternoon Shift: Continue** 

#### **Exhaust to CTO**

# #4 RC / 5202:

Continued to feed. Have been running with a discharge rate around 400 without any leaks. Many attempts have been made to run above 600, but the feed end has leaked every time.

Midnight shift: continue feeding

Day Shift:

**Afternoon Shift: Continue** 

#### **Exhaust to Trimer**

# #5 RC / Cu-3818:

Running 3818 again. Make sure temps are correct and follow MOD. Found parts of a C-Clamp in feed screw

Midnight Shift: feeding

Day shift:

Afternoon shift: Walking through 2nd half afternoon shift, will start feeding if

temps stay up.

#### **Exhaust to 5A DC**

# #6 RC & Dryer / D-0257

Use Auto Sampler for bags.

Midnight shift: running

Day Shift:

Afternoon shift: Restarted feed

**Exhaust to Sly Scrubber** 

# **6 Tank /D-5253 empty**

Continue. Drain looked at by Schirmer and Lucas- not fixed yet

Midnight Shift: no activity **Day Shift: No activity** Afternoon shift: NA

## New Pfaudler / D 5253 done

Pfaudler glass was inspected Friday.

Midnight Shift: No change. **Day Shift: No activity** Afternoon Shift: NA

# 7 Tank AMT, KLP solution next?

Hold Eliott advised that radar gauge on tank is not working. Will need repaired.

No other activity at this time

Midnight Shift: NA Day Shift: NA Afternoon shift: NA

## Old Pfaudler / D-0257:

Starting 1st batches and working on getting #6 finished for firing up make sure buggies are clean and available. Water pick up for lot 16 is .82, and for lot 17 is .80.

Midnight Shift: Made batch

**Day Shift:** 

Afternoon shift: Midnight shift batch in buggies but no activity, will schedule

midnight shift to make next batch

## **National Dryer:**

Schirmer finished bead blasting.

Midnight Shift: NA Day shift: NA Afternoon Shift: NA

# PK Blender/X 1000 repacks:

PK Clean and ready for repacks

Midnight Shift: holding for modifications to pk

Day shift:

Afternoon shift: Hold until morning (DL Page may modify PK outlet to

accommodate north end IBC totes - totes too tall).

# Abbe Blender / 5206 Done

Done for a while. Area Cleaned

Midnight shift: NA Day shift: NA

Afternoon shift: NA

# **Tower 3/ Cu 0860:**

Running, instructed to produce through batch 332- verify alcohol is onsite before loading 333.

Midnight Shift: Tower on nitrogen due to Mass Spec issues

Day shift:

Afternoon shift: Running, should unload day shift Tuesday

# **Tower 6 / Pd 1930:**

Pd 1930 material here for repacking...schedule as needed before each tower load. Reuse drums, if drums are in good condition, black out labels with spray paint and put new label on drum. 30 drum tower loads.

Midnight Shift: Tower on Nitrogen due to mass spec issues

Day shift:

Afternoon shift: Reloaded, continue. Working on drum leveling during midnight

shift

## North Screener / Cu-0860:

Change to Cu-0860. Keep running WOW for leaking Pump

Midnight shift: Continue Day shift: Continue

Afternoon shift: Continue

## South Screener / Cu-0860:

Change to Cu-0860. Keep running, WOW for leaking Pump

Midnight shift: Continue Day shift: Continue

**Afternoon Shift: Continue** 

# #2662 (west) Pill Machine / Al-3915 T 5/32:

Running, when able.

Midnight shift: continued

Day Shift:

Afternoon shift: Hold, restart midnight shift

# #2664 (east) Pill Machine / Al-3915 T 5/32:

Running, when able.

Midnight shift: continued

Day Shift:

Afternoon shift: Hold, restart midnight shift

# TK #2 / V 2046/V 2010:

Down for now. Will need to be switched to V-2010 Saggers...will discuss next

week

Midnight shift: Down
Day Shift: Down

**Afternoon shift: Down** 

# TK #4 / Cu 2508 next:

Lighting kiln Monday afternoon, changing saggers over

Midnight shift: Down carts not advancing

Day Shift:

Afternoon shift: Kiln lit and on low temp, car mover not advancing (Charlie Fern

notified). Fern worked on car puller but not certain if working properly.

Separate work order submitted – may need additional help on Tuesday as main

cable/chain may need adjusting. For now, kiln is down until this is

corrected...Abe Ahmed notified at 9:30 pm Monday.

# Harrop Kiln / Al 3920:

Al 3920 - 90 min Cart- operator must keep area cleaned

Midnight shift: Continue Day Shift: Continue

Afternoon shift: Continue

# **Building 27 Belt Filter / 5020:**

Set up for Cu-5020.

Midnight shift: Pill machine operator to watch for full bags off dryer and inform

Calciner operators to change bags out.

Day shift:

Afternoon Shift: Running, continue midnight shift

#### **Priorities:**

Priorities 1 through 12 are basically all the same priority, should be considered urgent and will require call outs for maint issues and/or processing issues.

- 1) #3 MED/#3RC/CTO
- 2) East Pfaudler/HC-11 Dryer/#6 RC
- 3) #4 Tunnel Kiln/Mill
- 4) #1 Line/#1RC
- 5) Harrop Kiln
- 6) Horne Tabletting
- 7) #5 RC
- 8) #4RC
- 9) South PK
- 10) #4 RC
- 11) Reduction Towers
- 12) Reduction Tower Screeners
- 13) South Precip

Al-3915 and Al-3920 are starting to move up the list, we are projecting to be late to our commitment to Seneca in delivering the AL-3920 by year end.

In reviewing their plan, we can be ~1 week late at most before it affects them, which in turn affects when the material returns for reduction, which places the burden on us to still meet the QVAM ship date.

Projected end date on the Al-3920 T is showing as Jan 5th.

#### **Maintenance & Other**

- 1) #2 Line will be down until Monday at least for spiral repairs #2RC test out new syntron controls while line is down DONE
- 2) Acid wash new pfaudler for repairs week of December 15 DONE
- 3) Vacuum national drier best as possible to soda blast next week Done
- 4) Drop tower 6 bottom and sheave change Monday December 8. Reinstalled
- 5) Need to clean and acid wash T4 and T-6 in Building 27 for checks. timing TBD based on how much 6081 we need to finish and when. Val also needs a week for punchlist items

# **Shipments to finish for December**

- 1) D5253 wraps up this weekend, analyze and ship ASAP
- 2) D-0756 finishes mid December need a plan to ship without final metals analysis ( TDR with ART?)
- 3) V-2046 told Tim C we would target a min of 25K week of Dec 22 with the last week of the month as a fallback, which I would like to avoid.
- 4) Cu-0860 drum fix DONE